

WEBB WHEEL PRODUCTS, INC.

2310 Industrial Drive, S.W. Cullman, Alabama 35055 (256) 739-6660

FAX: (256) 739-6246

April 23, 2001

SERVICE BULLETIN # 66

FLANGE NUT CHANGE

179955 Replaced by 179933

The purpose of this bulletin is to advise that effective with depletion of inventory, the flange nut furnished with our eight (8) stud hubs designed for pilot mount applications, part number 179955 (M22 X 1.5, 38mm Hex Size, 1.37 height) will be replaced by our 179933 Flange Nut (M22 X 1.5, 33mm Hex Size, 1.22 height).

This change will reduce our inventory of different nuts and at the same time reduce the costs of eight stud hub assemblies ordered with nuts.

Effective May 1, 2001 the add on for flange nuts shown in our price lists will change as shown below.

From: Assemblies \$ 7.50 To: Assemblies \$ 6.00

Service Assemblies \$ 10.00 Service Assemblies \$ 8.00

We would also like to advise of a new **flange nut add-on** for hubs using Disc Brake Rotors.

8 Stud Hub

Assemblies \$ 8.00 Service Assemblies \$ 8.00

If you have any questions regarding this change please contact us at the address and phone number shown in this bulletin or at sales@webbwheel.com.