



SERVICE BULLETIN #132

4/30/2015

Assembly Consolidation

Effective immediately, Webb Wheel is consolidating all loose hubs and low volume assemblies. These loose hubs and assemblies will continue to be offered as service assemblies, however some will require the studs and fastening hardware (if applicable) to be ordered separately. A comprehensive list is included with this document detailing the assembly order code which has been discontinued, the new ordering code, and the corresponding stud and drum/rotor (if applicable) for the obsolete assembly. If you have any questions, please contact the Webb Engineering department via email to engineering@webbwheel.com or call (256)739-6660.

Obsolete Order Code	Replacement Order Codes		
	Assembly	Stud	Drum/Rotor
10209--MLT	10209--NT	159183	--
10209--MRT	10209--NT	159184	--
10519CLAL-10*	10519--MLT80	Included	63631F
10519CLAR-10*	10519--MRT80	Included	63631F
10519--ML*	10519--MLT80	Included	--
10519--MR*	10519--MRT80	Included	--
10569--ML*	10569--NT80	139913	--
10569--MLT80*	10569--NT80	139913	--
10569--MR*	10569--NT80	139902	--
10569--MRT80*	10569--NT80	139902	--
12213BEAL-10*	12213--ML	139913	62200F
12213BEAR-10*	12213--MR	139902	62200F
12513--ML*	12513--N	139913	--
12513--MR*	12513--N	139902	--
1320Z--ML	1320Z--NT	159183	--
1320Z--MLT	1320Z--NT	159183	--
1320Z--MR	1320Z--NT	159184	--
1320Z--MRT	1320Z--NT	159184	--
1521F--PL	1521F--NT	100181	--
1521F--PLT	1521F--NT	100181	--
1521F--PLTP	1521F--NT	100181	--
1521F--PR	1521F--NT	100170	--
1521F--PRT	1521F--NT	100170	--
1530G--PL	1530G--NT	100181	--
1530G--PLT	1530G--NT	100181	--
1530G--PR	1530G--NT	100170	--
1530G--PRT	1530G--NT	100170	--
15501--ML	15501--N	159191	--
15501--MR	15501--N	159190	--
15501XUML*	15501--N	159191	54770P-65
15501XUMR*	15501--N	159190	54770P-65
20231--3T-MA	20231--OT-MA	101162	--
20231--FLT	20231--OT	101171	--
20231--FRT	20231--OT	101170	--
20231RJ5T*	20231--5T	Included	76864F
20231UH3T*	20231--3T	Included	66884F
20231UH4T*	20231--3T	Included	66884F
20231UH5T*	20231--5T	Included	66884F
20231UHMLT*	20231--OT	101171	66884F
20231UHMRT*	20231--OT	101170	66884F
20231UQ3*	20231--3T	Included	66864F

Obsolete Order Code	Replacement Order Codes		
	Assembly	Stud	Drum/Rotor
20231UQ4T*	20231--3T	Included	66864F
20231UQ4T-10*	20231--3T	Included	66864F
20231UQ5T*	20231--5T	Included	66864F
20231UQ6T*	20231--5T	Included	66864F
20231UQ6T-10*	20231--5T	Included	66864F
20231UQALT-10*	20231--MLT	Included	66864F
20231UQART-10*	20231--MRT	Included	66864F
20231UQMLT*	20231--MLT	Included	66864F
20231UQMRT*	20231--MRT	Included	66864F
20231VA5T*	20231--5T	Included	V1F
20231VAALT-10*	20231--MLT	Included	V1F
20231VAART-10*	20231--MRT	Included	V1F
20231VAMLT*	20231--MLT	Included	V1F
20231VAMRT*	20231--MRT	Included	V1F
20271--3	20271--0	101162	--
20271--3T	20271--0T	101162	--
20271--5	20271--0	101160	--
20271CW3*	20271--0	101162	63680F
20271CW3T80*	20271--0T80	101162	63680F
20271CW4*	20271--0	101162	63680F
20271CW4T80*	20271--0T80	101162	63680F
20271CW5*	20271--0	101160	63680F
20271CW5T80*	20271--5T80	Included	63680F
20271CW6T80-10*	20271--5T80	Included	63680F
20281--3	20281--3T	Included	--
20281--5	20281--5T	Included	--
23231--3	23231--3T	Included	--
23231--5	23231--5T	Included	--
23231--ML	23231--OT	101173	--
23231--MLT	23231--OT	101173	--
23231--MR	23231--OT	101172	--
23231--MRT	23231--OT	101172	--
23231UH3*	23231--3T	Included	66884F
23231UH3T*	23231--3T	Included	66884F
23231UH5*	23231--5T	Included	66884F
23231UH5T*	23231--5T	Included	66884F
23231UQ3T*	23231--3T	Included	66864F
23231UQ4-10*	23231--3T	Included	66864F
23231UQ4T-10*	23231--3T	Included	66864F
23231UQ5*	23231--5T	Included	66864F
23231UQ5T*	23231--5T	Included	66864F

Obsolete Order Code	Replacement Order Codes		
	Assembly	Stud	Drum/Rotor
23231UQAL-10*	23231--OT	101173	66864F
23231UQAR-10*	23231--OT	101172	66864F
23431--3	23431--3T	Included	--
23431--3T-MA	23431--OT-MA	101162	--
23431--MLT	23431--OT	101171	--
23431--MRT	23431--OT	101170	--
23431UQ3T*	23431--3T	Included	66864F
23431UQ5T*	23431--5T	Included	66864F
23431VA3T*	23431--3T	Included	V1F
23431VA5T*	23431--5T	Included	V1F
23481--3	23481--OT	101162	--
23481--3T	23481--OT	101162	--
23481--5T	23481--OT	101160	--
24011--3	24011--3T	Included	--
24011--5	24011--OT	101160	--
24011--5T	24011--OT	101160	--
24011--ML	24011--OT	101173	--
24011--MLT	24011--OT	101173	--
24011--MR	24011--MRT	Included	--
24011UH3*	24011--3T	Included	66884F
24011UH4*	24011--3T	Included	66884F
25201--1	25201--1T	Included	--
25201--1TP	25201--1T	Included	--
25201--3	25201--3T	Included	--
25201--3TP	25201--3T	Included	--
25201--PL	25201--OT	101175	--
25201--PLT	25201--OT	101175	--
25201--PRT	25201--OT	101174	--
25261--1T	25261--OT	101164	--
25261--3T	25261--OT	101162	--
25301--1	25301--1T	Included	--
25301--1TP	25301--1T	Included	--
25301--3	25301--OT	101162	--
25301--3T	25301--OT	101162	--
25301--7	25301--OT	101161	--
25301--7T	25301--OT	101161	--
25301--7TP	25301--OT	101161	--
25301--PL	25301--OT	101175	--
25301--PLT	25301--OT	101175	--
25301--PR	25301--OT	101174	--
25301--PRT	25301--OT	101174	--

* May require additional fastening hardware to be purchased. Please contact the Webb Wheel Customer Service department if you have any questions.



SERVICE BULLETIN #132

Obsolete Order Code	Replacement Order Codes		
	Assembly	Stud	Drum/Rotor
25301--TL	25301--OT	101179	--
25301--TLT	25301--OT	101179	--
25301--TR	25301--OT	101178	--
25301--TRT	25301--OT	101178	--
25301--TRTP	25301--OT	101178	--
25331--1T	25331--OT	101164	--
25331--3T	25331--OT	101162	--
25401--1	25401--OT	101164	--
25401--1T	25401--OT	101164	--
25401--3	25401--OT	101162	--
25401--3T	25401--OT	101162	--
25401--7	25401--OT	101161	--
25401--PL	25401--PLT	Included	
25401--PR	25401--PRT	Included	--
25411--1T	25411--OT	101164	--
25411--3T	25411--OT	101162	--
25421--3T	25421--OT	101162	--
25501--3	25501--0	101191	--
25801--PLT	25801--NT	100181	--
25801--PRT	25801--NT	100170	--
25851--1T	25851--OT	101193	--
25851--3T	25851--OT	101164	--
26051--3	26051--0	101162	--
26061--1	26061--0	101164	--
26061XU1*	26061--0	101164	54770P-65
26081--3T	26081--OT	101162	--
26081--5T	26081--OT	101160	--
26141--3	26141--OT	101162	--
26141--3T	26141--OT	101162	--
26141--5T	26141--OT	101160	--
26141--MLT	26141--OT	101173	--
26141--MRT	26141--OT	101172	--
26231--MRT	26231--OT	101172	--
26301--5	26301--0	101160	--
26331--3	26331--OT-71	101162	--
26331--3T	26331--OT-71	101162	--
26331--3T-71	26331--OT-71	101162	--
26331--5T-71	26331--OT-71	101160	--
26351--3T	26351--OT	101162	--
26351--5T	26351--OT	101160	--
26351--5T-71	26351--OT-71	101160	--

Obsolete Order Code	Replacement Order Codes		
	Assembly	Stud	Drum/Rotor
26361--3	26361--OT	101162	--
26361--3T	26361--OT	101162	--
26361--5T	26361--OT	101160	--
26361--6-10	26361--OT	101160	--
26381--3	26381--0	101164	--
26381XP3*	26381--0	101164	54775P-65
26431--3	26431--3T	Included	--
26431--4T	26431--3T	Included	--
26431--5	26431--5T	Included	--
26431--6	26431--5T	Included	--
26431--6T	26431--5T	Included	--
26431--ML	26431--MLT	Included	--
26431--MR	26431--MRT	Included	--
26431RH3T*	26431--3T	Included	66884B
26511--3T	26511--OT	101162	--
26511--5T	26511--OT	101160	--
26511--5TP	26511--OT	101160	--
26511--MLT	26511--OT	101173	--
26511--MLTP	26511--OT	101173	--
26511--MLTP	26511--OT	101173	--
26511--MRT	26511--OT	101172	--
26511--MRTP	26511--OT	101172	--
26531--1T	26531--OT	101164	--
26531--3	26531--3T	Included	--
26531--5	26531--OT	101160	--
26531--5T	26531--OT	101160	--
26531--MLT	26531--OT	101173	--
26531--MR	26531--OT	101172	--
26531--MRT	26531--OT	101172	--
26561--1T	26561--OT	101164	--
26561--5	26561--OT	101160	--
26561--5T	26561--OT	101160	--
26561--MLT	26561--OT	101173	--
26561--MRT	26561--OT	101172	--
27231--3	27231--3T	Included	--
27231--5T	27231--OT	101160	--
27231--7T	27231--OT	101161	--
27231MH3*	27231--3T	Included	66661B
27231--MLT	27231--OT	101173	--
27231--MRT	27231--OT	101172	--

*May require additional fastening hardware to be purchased. Please contact Webb Wheel Customer Service department if you have any questions.