

SERVICE BULLETIN #151

6/4/2018

Obsolete Part Numbers

Because of a decline in sales, the following part numbers are being obsoleted with inventory. Webb Wheel Products will continue to offer replacement options for these hub assemblies, however some assemblies will require the wheel studs to be ordered separately. Please see replacement order codes listed below. If you have any questions regarding this change, please contact our technical service department via email to engineering@webbwheel.com.

Obsolete Order Code	Replacement Order Code	Replacement Wheel Studs
20281—0T	202710T-71	Studs Included
20281—3T	202710T-71	101162 (8 pcs.)
20281—5T	202710T-71	101160 (8 pcs.)
23481—0T	234710T	N/A